



# Albi

**Albi Manufacturing**  
 Division of StanChem, Inc.  
 401 Berlin St., East Berlin, CT 06023  
 860/828-0571 Fax: 860/828-3297  
<http://www.albi.com> [info@albi.com](mailto:info@albi.com)

## ALBI DRICLAD

### Underwriters' Laboratories Listings

page 1 of 2

#### **COLUMNS: Wide Flange**

**FIRE TEST: ASTM E-119**

COLUMN SIZE	U.L. DESIGN NO.	HOURLY RATING	MATERIAL THICKNESS
W10 x 49	X-313	1 hr.	3/4 in.
	X-313	1-1/2 hrs.	1-1/4 in.
	X-313	2 hrs.	1-1/2 in.
	X-313	3 hrs.	2-1/2 in.
W12 x 120	X-313	4 hrs.	1-1/2 in.

#### **BEAMS: Roof / Ceiling (restrained & unrestrained)**

**FIRE TEST: ASTM E-119**

BEAM SIZE	U.L. DESIGN NO.	HOURLY RATING	MATERIAL THICKNESS
W8 x 31	S-301	1 hr.	3/4 in.
	S-301	1-1/2 hrs.	3/4 in.
	S-301	2 hrs. (restrained)	3/4 in.
	S-301	2 hrs. (unrestrained)	1-5/8 in.
	S-301	3 hrs. (restrained)	1-5/8 in.

#### **BEAMS: Floor / Ceiling (restrained & unrestrained)**

**FIRE TEST: ASTM E-119**

BEAM SIZE	U.L. DESIGN NO.	HOURLY RATING	MATERIAL THICKNESS
W8 x 31	N-307	1 hr.	3/4 in.
	N-307	1-1/2 hr.	3/4 in.
	N-307	2 hrs. (restrained)	3/4 in.
	N-307	2 hrs. (unrestrained)	1-5/8 in.
	N-307	3 hrs. (restrained)	1-5/8 in.

#### **BEAMS: Unprotected Roof/Ceiling (restrained & unrestrained)**

**FIRE TEST: ASTM E-119**

BEAM SIZE	U.L. DESIGN NO.	HOURLY RATING	MATERIAL THICKNESS
W8 x 31	P-930	1 hr.	3/4 in.
	P-930	1-1/2 hrs.	3/4 in.
	P-930	2 hrs. (restrained)	3/4 in.
	P-930	2 hrs. (unrestrained)	1-5/8 in.

#### **BEAMS: Protected Roof / Ceiling (restrained & unrestrained)**

**FIRE TEST: ASTM E-119**

COLUMN SIZE	U.L. DESIGN NO.	HOURLY RATING	MATERIAL THICKNESS
W8 x 31	P-302	1 hr.	1 in.

#### **ASSEMBLY: Floor / Ceiling (restrained)**

**FIRE TEST: ASTM E-119**

COLUMN SIZE	U.L. DESIGN NO.	HOURLY RATING	MATERIAL THICKNESS
W8 x 31	D-929	1 hr.	3/4 in.
	D-929	1-1/2 hr.	3/4 in.
	D-929	2 hrs.	3/4 in.
	D-929	3 hrs.	1-5/8 in.



# Albi

**Albi Manufacturing**  
 Division of StanChem, Inc.  
 401 Berlin St., East Berlin, CT 06023  
 860/828-0571 Fax: 860/828-3297  
<http://www.albi.com> [info@albi.com](mailto:info@albi.com)

## ALBI DRICLAD

Underwriters' Laboratories Listings

page 2 of 2

### **ASSEMBLY: Floor / Ceiling (unrestrained)**

**FIRE TEST: ASTM E-119**

BEAM SIZE	U.L. DESIGN NO.	HOURLY RATING	MATERIAL THICKNESS
W8 x 31	D-929	1 hr.	3/4 in.
	D-929	1-1/2 hr.	3/4 in.
	D-929	2 hrs.	1-5/8 in.

### **ASSEMBLY: Protected Floor / Ceiling (restrained & unrestrained)**

**FIRE TEST: ASTM E-119**

BEAM SIZE	U.L. DESIGN NO.	HOURLY RATING	MATERIAL THICKNESS
W8 x 31	D-303	1 hr.	3/4 in.
	D-303	1-1/2 hr.	3/4 in.
	D-303	2 hr. (restrained)	3/4 in.
	D-303	2 hr. (unrestrained)	1-5/8 in.
	D-303	3 hr. (restrained)	1-5/8 in.

### **ASSEMBLY: Floor / Ceiling (restrained & unrestrained)**

**FIRE TEST: ASTM E-119**

BEAM SIZE	U.L. DESIGN NO.	HOURLY RATING	MATERIAL THICKNESS
W8 x 31	G-301	3 hr.	1 in.

### **ASSEMBLY: Protected Floor / Ceiling (restrained & unrestrained)**

**FIRE TEST: ASTM E-119**

BEAM SIZE	U.L. DESIGN NO.	HOURLY RATING	MATERIAL THICKNESS
W8 x 31	J-301	1 hr.	3/4 in.
	J-301	1-1/2 hr.	3/4 in.
	J-301	2 hr. (restrained)	3/4 in.
	J-301	2 hr. (unrestrained)	1-5/8 in.
	J-301	3 hr. (restrained)	1-5/8 in.